

49 Secure Plug




50 Interior Wall With Coating Loss, Exposed Underlying Steel, Mild Surface Corrosion And Mild To Moderate Staining



51 Interior Wall With Coating Loss, Exposed Underlying Steel, Mild Surface Corrosion And Mild To Moderate Staining



Interior Wall With Coating Loss, Exposed Underlying
Steel, Mild Surface Corrosion And Mild To Moderate
Staining



53 Interior Wall With Coating Loss, Exposed Underlying Steel, Mild Surface Corrosion And Mild To Moderate Staining



54 Interior Wall With Coating Loss, Exposed Underlying Steel, Mild Surface Corrosion And Mild To Moderate Staining